
21 STATE CIRCLE SHAW HOUSE	NEGATIVE FILE NUMBER: 1/2/2 D-629
AMNAPOLIS, MARYLAND 21401	η
HISTORIC SITES SURVEY FIELD SHEET	CTM REFERENCES: Zone/Easting/Northing
Individual Scructure Survey Form	Westernasting/Northing
And the second s	I I C C C -OHER WIN
The second secon	U.S.G.S. QUAD. MAP:
	PRESENT FORMAL NAME:
CC_NTY: Dorchester TOWN: East New Market .:	ORIGINAL FORMAL NAME:
LOCATION: School Street	
Route 14	PRESENT USE:
East New Market	ARCHITECT/ENGINEER:
COMMON NAME: BUNK MIUS HOUSE	ENGINEER:
FUNCTIONAL TYPE: dwelling/residential	BUILDER/CONTRACTOR:
OWNER: Mr. and Mrs. "Bunk" Mills	!! CHRISTINA AND AND
ADDRESS: same as above	PHYSICAL CONDITION OF STRUCTURE.
	Good ()
ACCESSIBILITY TO PUBLIC:	Fair (Poor: ()
Yes(x) No () Restricted() LEVEL OF SIGNIFICANCE:	STYLE:
	DATE BUILT:
Local() State() National() GENERAL DESCRIPTION:	1892
Structural System	
1. Foundation: Stone (Vertal ()	
1. Foundation: Stone()Brick()Conc. 2. Wall Structure	rete()Concrete Block()
A. Wood Frame: Post and Beam()Balloon(X)	
and bearing Masonry: Brick/ \c.	
C. Iron() D. Steel() E. Other:	
3. Wall Covering: Clapboard()Board and Batten()Wood Shingle()Shiplap() Novelty()Stucco()Sheet Metal()Aluminum(X)Asphalt Shingle() Brick Veneer()Stone Veneer()	
boilding Pattern:	i
1 . seractate	Other:
B. Other:	
5. Roof Covering: Slate()Wood Shingle()Asphalt Shingle(X)Sheet Metal() Built Up()Rolled()Tile()Other:	
Built Up()Rolled()Tile()Other: 6. Engineering Structure 6. Engineeri	
7. Other: A structure:	
Appendages: Porches(') Towers()Complex()P	
Appendages: Porches(*)Towers()Cupolas()Dormers()Chimneys()Sheds()Ells()	
Koor Style: Cable(X)Hip()Shed()Flor()V	
Saw Tooth()With Monitor()With Bellcast()With Parapet()With False Front()	
Number of Stories: 2	() with False Front()
Number of Bays: 2	
Approximate Dimensions: 2×2	Entrance Location: 151
212	
THREAT TO STRUCTURE:	
No Threat()Zoning()Roads()	LOCAL ATTITUDES:
Development()Deterioration()	Positive(x)Negative() Mixed() Other:
Alteration (X)Other:	Mixed() Other:
	ì

ELATED STRUCTURES: (Describe)

TATEMENT OF SIGNIFICANCE:

PERENCES:

P: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

Open Lane()Woodland()Scattered Buildings()
Moderately Built Up(x)Densely Built Up()
Residential()Commercial()

Agricultural()Industrial()

Roadside Strip Development()
Other:

LADC

RECORDED BY:

East New Market Historic District Commission ORGANIZATION:

Summar, 1985.

DATE RECORDED:

Sara Rossing

PROPERTY OF MR. AND MRS. "Bunk" MILLS


2-story, gabled, asphalt tile roof with a variety of additions, including window styles and sizes. Windows in main block 2 over 2. 2 by 2 bay. Exposed rafters. 2 inside chimneys with one being very short. Brick foundation.

Note: FROM BETWEEEN THE NANTICOKE AND THE CHOPTANK

"Christina Andrew House, East New Market, 1892, Private Much of the original fabric of this house has been obscured by modern siding and an unattractive metal porch. It was built in 1892 by Christina Andrew, whose husband, Tilghman Andrew, had bought the property in 1879

Generally, the simple vernacular houses along the southern part of Maryland Route 14 are smaller and less imposing than the dwellings built at the turn of the century in the northern part of East New Market."

EAST NEW MARKET QUADRANGLE MARYLAND 7.5 MINUTE SERIES (TOPOGRAPIUS)





29

57%